

L&C Reroute Around Collapse

The big rain over the first weekend in May caused about 4' of bank to collapse and expose the tread to an 8' verticle drop, with an overall dropoff of 20'.



On May 18, a 100 foot reroute reestablished the trail on solid soil.

